

**HP OfficeJet Pro 9010 series****Fax Test Report for**  
Aug 21 2024 1:44pm

---

Fax Hardware Test	<b>PASS</b>
Fax Connected to Active Telephone Wall Jack	<b>PASS</b>
Phone Cord Connected to Correct Port on Fax	<b>PASS</b>
Using Correct Type of Phone Cord with Fax	<b>PASS</b>
Dial Tone Detection	<b>PASS</b>
Fax Line Noise Test	<b>PASS</b>
Fax Line Condition Test	<b>PASS</b>
Your Company Name:	<b>FAX</b>
Phone Number	<b>8176725882</b>

---

**Your HP device has passed the fax test.**

The fax settings can also affect the performance of your HP device.  
Please check your current fax settings listed below.

Language	English
Country/Region	USA
Auto Answer	On
Rings to Answer	2
Paper Size	Letter
Tone or Pulse Dialing	Tone Dialing
Fax Volume	Soft
Distinctive Ring	Double Rings
Busy Redial	Redial
No Answer Redial	No Redial
Automatic Reduction	On
Backup Fax Reception	On
(ECM) Error Correction Mode:	On
Speed	Medium (14400)
Fax Forwarding	Off
Connection Problem Redial	Redial

Refer to your User Guide for more information on the fax test and settings.

---

## Instructions on how to rerun this test:

- Step 1. Press the "Fax" button
- Step 2. Choose the "Setup" menu
- Step 3. Choose the "Tools" menu
- Step 4. Choose the "Run Fax Test" menu

TH38V780NC

MANHTNPP1N005.2242A.00