

HP OfficeJet Pro 8030 series**Fax Test Report for**
Nov 20 2023 8:10pm

Fax Hardware Test	PASS
Fax Connected to Active Telephone Wall Jack	PASS
Phone Cord Connected to Correct Port on Fax	PASS
Using Correct Type of Phone Cord with Fax	PASS
Dial Tone Detection	PASS
Fax Line Noise Test	PASS
Fax Line Condition Test	PASS
Your Company Name:	bob and ann marie
Phone Number	4015685768

Your HP device has passed the fax test.

The fax settings can also affect the performance of your HP device.
Please check your current fax settings listed below.

Language	English
Country/Region	USA
Auto Answer	On
Rings to Answer	6
Paper Size	Letter
Tone or Pulse Dialing	Tone Dialing
Fax Volume	Soft
Distinctive Ring	All Rings
Busy Redial	Redial
No Answer Redial	No Redial
Automatic Reduction	On
Backup Fax Reception	On
(ECM) Error Correction Mode:	On
Speed	Medium (14400)
Fax Forwarding	Off
Connection Problem Redial	Redial

Refer to your User Guide for more information on the fax test and settings.

Instructions on how to rerun this test:

- Step 1. Press the "Fax" button
- Step 2. Choose the "Setup" menu
- Step 3. Choose the "Tools" menu
- Step 4. Choose the "Run Fax Test" menu

TH1582R0CG

MALBECPP1N004.2330B.00