

PACKAGING YOUR RYOBI BATTERY PACK FOR SERVICE

PLEASE NOTE: Per DOT/PHMSA, the shipment of your lithium-ion battery will require special packaging and labeling. For full shipping instructions and guidelines, please visit <http://www.phmsa.dot.gov/>. Please follow these steps in preparing the return shipment of your battery:

1. Place tape over the terminals of your battery as shown
2. Place your battery in a sealable plastic bag
3. Place bagged battery in a strong corrugated carton with sufficient packing materials to assure battery does not shift and remains protected during shipment
4. Print ICAO lithium-ion battery handling label (label outlined in red on included sheet) in full size and color and apply to a side of the box with clear packing tape, insuring that the label does not overlap any seams of the box
5. Print black and white lithium-ion label, place in packing slip pouch, and adhere to side of box. A pouch may be obtained at your local FedEx drop-off location
6. Print FedEx shipping label and adhere to side of the box with clear packing tape and take package to local FedEx drop-off location for shipment. The location nearest to you can be located at <http://www.fedex.com/locate/>

NOTE: Only one battery may be shipped per box.

